

APPENDIX C

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 1: Clearing and grubbing activity with Hydro-Ax.



Photo 2: Gamma walk over survey activity performed with a buggy-mounted instrument.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 3: Gamma walk over survey equipment mounted on a Gator.



Photo 4: Floor grid in Building 4/9 establish for scan survey.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 5: Surface scanning, direct measurement, and swipe testing of building exterior.



Photo 6: Surface scanning, direct measurement, and swipe testing of building exterior.



Photo 7: Surface scanning, direct measurement, and swipe testing of building interior.



Photo 8: Low flow groundwater sampling activities at MW-08.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 9: Low flow groundwater sampling activities at MW-5.



Photo 10: Aquifer testing activities at MW-605D.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 11: Aquifer testing activities at MW-23.



Photo 12: Sediment and water column sampling activities at the Erie Canal.



Photo 13: View northwest of the Guterl Steel pump house and outfall.



Photo 14: Surface water sampling activity in Building 2.



Photo 15: Surface water sampling activity at culvert on the west side of Building 4/9.



Photo 16: Sediment sampling activity a catch basin located on the east side of Building 24.



Photo 17: Sampling activities of a sink drain.



Photo 18: Concrete coring activity in Building 4/9.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 19: DPT sampling activity on the south side of Building 14.



Photo 20: DPT sampling activities with a track-mounted rig in Building 6.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 21: Core management activities.



Photo 22: DPT sampling activities with a truck-mounted rig on the west side of Building 24.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 23: Soil cores collected with direct push technology rig prepared for core scanner.



Photo 24: Soil core scanning activity.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 25: Building material samples collected for laboratory analysis.



Photo 26: Soil sample archiving activities.

Guterl Steel RI Report
Remedial Investigation Photographs



Photo 27: Drum storage containment pad in Building 35.



Photo 28: Loading IDW drums into truck for off site disposal.