

## **APPENDIX W**

## PHOTOS - Parcel IAO1 & IAO2



Photo 1 – View of the abandoned buildings and access ways within the parcel.



Photo 2 – View of the abandoned rail spur and opportunistic vegetation within the parcel.

## PHOTOS - Parcel IAO3



Photo 1 – View of the upland young fields within the parcel.



Photo 2 – Common reed wetlands in the western portion of the parcel. The area appears to be semi-maintained/ mowed.



Photo 3 – Wet depressional areas within the southern portion of the parcel. Wetlands may be ephemeral depending on annual level or precipitation and level of disturbance.

## PHOTOS - Parcel IAO4



Photo 1 – Photo of the access roads and factories that comprise the central portion of the site.



Photo 2. View of emergent wetlands near Bldg 3. The vegetation in the ditch is dominated by hydric species (e.g., cattails, horsetail, etc.). The ditch drains south to the wooded area and wetlands in the southern portion of the parcel.



Photo 3 – View of the young field located in the northwest portion of the parcel.

## PHOTOS - Parcel IAO4



Photo 4 – View of a wet depressional area northwest of Bldg 35. The area is associated with a drainage swale.



Photo 5 – View of maintained grass lawns and ornamental tree species in the southeast portion of the site.



Photo 6 – View of the remnant paved area east of Ohio Street in the extreme southeast portion of the parcel.

## PHOTOS - Parcel IAO4



Photo 7 – View of the wooded area and fields south of Bldg 14.



Photo 8 – View of emergent, scrub/shrub, forested wetlands in the southeast portion of Parcel IAO4.



Photo 9 – View of the drainage swale located east of the Rt 93 bypass.

# PHOTOS - Parcel IAO4



Photo 10 – View of the drainage ditch that is west of the Rt 93 Bypass.



Photo 11 – View of the pipes that appear to connect the ditch east of the Rt 93 Bypass (left) with the ditch that is west of the Bypass (Right).



Photo 12 – View of the young field in the northeast portion of the parcel.

## PHOTOS - Parcel IAO5



Photo 1 – View of the semi-maintained fields and small wooded area in the parcel.



Photo 2 – View of wet depressional areas within the abandoned railroad bed.



## PHOTOS - Parcel IAO9



Photo 1 - View of the Erie Canal. Note the vertical, cut bedrock banks.