

Post-Remedial Action Report
First Floor Offices and Small Hallway
Figure 4.5-1
Summary of Contamination and Remedial Actions

Linde Site, Tonawanda, New York

Bechtel National, Inc.

FUSRAP Program

Date: 6/15/99

File: 129F146.DGN

Job #: 14501-129

Site Map



LEGEND

A-2 Grid Coordinates (1 meter x 1 meter cells)

Floor area contaminated

SB-1 Soil borings

Building Walls