CONVERSATION RECORD

TIME: 3:15 pm

DATE: 1-10-89

TYPE

☐ VISIT ☐ CONFERENCE ☒ TELEPHONE

☒ INCOMING ☐ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	ORGANIZATION (Office, dept., bureau, etc.)	TELEPHONE NO.
Ted Gable	EPA, Region II	513-255-7717

SUBJECT

Former Lake Ontario Ordnance Works, RI/FS

ROUTING	
NAME/SYMBOL	INT

SUMMARY

Ted called to get the name and phone number of the Air Force contact regarding AF Plant 38. I told him John Neptune at Wright-Patterson AFB is the project manager for AF Plant 38, and that his phone number is Ted also indicated that he would telecopy the EPA comments to the RI report to KCD by the end of the week. Ted plans to call John and discuss the status of RCRA closures at AF Plant 38, and also the need for an RI/FS at the plant in order for the AF to be able to excess the property to GSA.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE	DATE
Lee Fuerst	Lee Fuerst	1-10-89

ACTION TAKEN

SIGNATURE	TITLE	DATE