CONVERSATION RECORD

TIME	DATE
2:00 pm	8-18-88

TYPE

☐ VISIT ☐ CONFERENCE ☒ TELEPHONE

☐ INCOMING ☒ OUTGOING

Location of Visit/Conference:

ROUTING	
NAME/SYMBOL	INT

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	ORGANIZATION (Office, dept., bureau, etc.)	TELEPHONE NO.
Dan Kraft	EPA - Region 2 - Edison Chief, TSCA & PSB, etc. group (Chemical Toxic Substances Group)	201-906-6817

SUBJECT

L. Ontario Ordnance Works

SUMMARY

I called Dan to determine why EPA was sampling for PCBs at the Somerset Group property. He indicated that on a visit to SCA Chemical Services offices he had noticed a couple of transformers lying on the Somerset Group property. They determined that under EPA PCB regulations they should inspect the transformers. Thus Dan sent 2 people to inspect the transformers and any other areas on the Somerset property worthy of review. Dan said that from the information on the nameplate, EPA feels that the empty transformers once contained oil, but probably not PCBs. EPA took samples from the sump near the old transformer pad. Dan believes the pit is filled mostly with water. He will provide the Corps with analytical results when they are available. I told Dan that the Corps plans to begin an RI on the Somerset property in the Spring of 1989, and that we planned to sample the sump at that time. Dan suggested that we take samples from the bottom of the pit. He also indicated that in order for Mr. Syms to be in compliance with environmental laws, the empty transformers should be disposed of properly, i.e. in a sanitary landfill.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE	DATE
Lee Fuerst	Lee Fuerst	8-19-88

ACTION TAKEN

SIGNATURE	TITLE	DATE