CONVERSATION RECORD

TIME: 10:00

DATE: 8-18-88

TYPE

☐ VISIT ☐ CONFERENCE ☒ TELEPHONE

☒ INCOMING ☐ OUTGOING

Location of Visit/Conference:

ROUTING	
NAME/SYMBOL	INT

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	ORGANIZATION (Office, dept., bureau, etc.)	TELEPHONE NO.
Ken Littlin	Acres	

SUBJECT

L. Ontario Ordnance Works

SUMMARY

Ken called to indicate that John Syms, Somerset Group, had called him to tell him that EPA-Region II personnel had visited his property on 17 August and took samples for PCB's at the sump near the old transformer pads. They also inspected the 2 transformers stored on the back part of his property. Apparently the samples were taken by lowering a jar tied to a string into the water. No samples were taken from the bottom of the sump. The two EPA personnel were David Greenlaw and Winston Lue, both from the EPA's Edison office. They deal primarily with TSCA and PCBs. Mr. Syms was curious why EPA decided to sample his property for PCBs at this time. EPA requested that he sign a notice of inspection, but Mr. Syms declined.

David Greenlaw 201-906-6817

Winston Lue

Dan Kraft (Supervisor)

ACTION REQUIRED

I called EPA to determine the status of PCB sampling at the Somerset Group property.

NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE	DATE
Lee Fuerst	Lee Fuerst	8-18-88

ACTION TAKEN

SIGNATURE	TITLE	DATE