



US Army Corps  
of Engineers®  
Buffalo District  
BUILDING STRONG®

# Safe Work Measures During Building G-1 Deconstruction




Harshaw Chemical Company Site Formerly Utilized Sites Remedial Action Program



Asbestos-Containing  
Material Survey



Air Monitoring




Dust Controls



Work Controls (Practices to  
Prevent Spread of Contamination)



Wastewater Control



Work Zones



Training



Radiological Survey



US Army Corps  
of Engineers®  
Buffalo District  
BUILDING STRONG®

# Deconstruction of Building G-1



Harshaw Chemical Company Site  
Formerly Utilized Sites Remedial Action Program



Geophysical Survey



Verify Utilities/Disconnect



Asbestos-Containing Material Abatement



Deconstruction



Waste Handling/Debris Loadout



Transport and Disposal



Post-Deconstruction Radiological Survey



Groundwater Investigation