



**DEPARTMENT OF THE ARMY**

BUFFALO DISTRICT, CORPS OF ENGINEERS  
1776 NIAGARA STREET  
BUFFALO, NEW YORK 14207-3199

REPLY TO:

**JUN 03 2010**

Executive Office

SUBJECT: Niagara Falls Storage Site FUSRAP Site Document Request

Honorable Louise M. Slaughter  
Representative in Congress  
3120 Federal Building  
100 State Street  
Rochester, NY 14614

Dear Representative Slaughter:

This correspondence serves as our response to your May 19, 2010 letter requesting copies of U.S. Department of Energy (USDOE) reference documents 4, 6, 7, 8, 10, 11, and 12 from the "Current Radiological Containment Status of Niagara Falls Storage Site (NFSS) – Building 401, 403, and the Soils Outside of Building 401" report. Below is a list of the reference documents that are enclosed in hard copy and electronically:

4. NFSS Building 401 Decontamination Status/Plan, dated August 22, 1996
6. NFSS, Building 401 – IVC's field notes, dated September 9-10, 1996
7. FUSRAP Data Transmittals D-27451 and D-27452 containing SEC radiological surveys, dated December 2, 1996
10. E-mail from C.R. Rieman to S.K. Amrit regarding NFSS Building 403 – Radiological contamination status as of April 10, 1997

We were unable to locate reference documents 8, 11, and 12 in our search of the microfiche provided to the U.S. Army Corps of Engineers by the USDOE in 1997. These documents are listed as references in other USDOE documents but do not appear to have been archived in the microfiche.

A copy of this letter without enclosures is being forwarded to your Washington, D.C. office. If you have any questions about these documents, please contact me at ( [REDACTED] )

Sincerely,

[REDACTED]

Lieutenant Colonel, Corps of Engineers  
District Commander

Enclosures

NFSS\_09.01\_0027\_a