



FACSIMILE MESSAGE

EA Engineering, Science, and Technology, Inc.
15 Loveton Circle
Sparks, Maryland 21152
410-771-4950 (tel) • 410-771-4204 (fax)

PLEASE DELIVER TO :

Name: Chuck Basham MARY OMARA
Company/Department: _____
Phone: _____ Fax (410) 962-2318
Subject: _____

If you do not receive all pages clearly, call _____ at Ext. _____ as soon as possible.

SENT BY:

Name: Gordy
Transmitting From: OMNIFAX G55 Number of Pages (including Transmittal Sheet): 6
Date: _____ Time: _____ Project No. _____
Task No.: _____ Dept No. _____

BRIEF MESSAGE:

To: Gordy Porter, EA Engineering, Sparks, MD

From: Jeff Smith, EA Engineering, Youngstown, N.Y.

Re: Area 7/8 Elevated Radiation Readings

Gordy,

Sandy asked me to provide you with the information relating to the suspect area between Areas 7 and 8 where we found elevated radiation counts. Attached is a drawing relating the suspect area with surrounding features. We have surrounded the area with caution tape and will not reenter. Please call me if you or anyone have any questions.

Thanks,

Jeff




EA ENGINEERING,
SCIENCE, AND
TECHNOLOGY, INC.

Project LEOW Contract No. _____

Subject Area 7/B elevated rad. readings Sheet No. 1 of 1

Drawing No. _____

Computed by JAS Date 9/22/00 Checked by _____ Date _____



Note:

Rad readings taken @
 30' & 100' from suspect
 area averaged 100 μ R/h.
 Rad readings within suspect
 area averaged 12,000 μ R/h
 with a peak of
 17,000 μ R/h.

§20.1902 Posting requirements.

- (a) *Posting of radiation areas.* The licensee shall post each radiation area with a conspicuous sign or signs bearing the radiation symbol and the words "CAUTION, RADIATION AREA."
- (b) *Posting of high radiation areas.* The licensee shall post each high radiation area with a conspicuous sign or signs bearing the radiation symbol and the words "CAUTION, HIGH RADIATION AREA" or "DANGER, HIGH RADIATION AREA."
- (c) *Posting of very high radiation areas.* The licensee shall post each very high radiation area with a conspicuous sign or signs bearing the radiation symbol and words "GRAVE DANGER, VERY HIGH RADIATION AREA."
- (d) *Posting of airborne radioactivity areas.* The licensee shall post each airborne radioactivity area with a conspicuous sign or signs bearing the radiation symbol and the words "CAUTION, AIRBORNE RADIOACTIVITY AREA" or "DANGER, AIRBORNE RADIOACTIVITY AREA "
- (e) *Posting of areas or rooms in which licensed material is used or stored.* The licensee shall post each area or room in which there is used or stored an amount of licensed material exceeding 10 times the quantity of such material specified in appendix C to part 20 with a conspicuous sign or signs bearing the radiation symbol and the words "CAUTION, RADIOACTIVE MATERIAL(S)" or "DANGER, RADIOACTIVE MATERIAL(S)."

[56 FR 23401, May 21, 1991, as amended at 60 FR 20185, Apr. 25, 1995]

[[CFR Index](#) | [Part 20 Index](#) | [NRC Home Page](#)]