

FLOOR FEATURES



SOIL BORING LOCATIONS



FLOOR FEATURES
AREA OF SOIL EXCAVATION

Site Map



LEGEND

- Excavated soil
- Mercury contaminated soil removed
- Location exceeding remedial action criteria
- LEC-14N-3 — Location exceeding remedial action criteria
- SB-16 — Delineation soil borings
- Building Walls
- A-2 — Grid Coordinates (1 meter x 1 meter cells)
- Trenches, sumps
- Drainpipe

Post-Remedial Action Report
Area 9

Figure 4.9-1
Summary of Remedial Activities

Linde Site, Tonawanda, New York

Bechtel National, Inc.
FUSRAP Program

Date: 6/15/99
File: 129F147.DGN
Job #: 14501-129