New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov



May 25, 2010

Mr. John Busse LOOW/NFSS Program Manager Department of the Army Buffalo District Corps of Engineers 1776 Niagara Street Buffalo, New York 14207-3199

Dear Mr. Busse:

Spill Number 0806523 Lake Ontario Ordnance Works Lewiston, Niagara County

This office has reviewed the post-excavation and geoprobe soil sample laboratory analysis results. The results exceed our soil guidance values. However, based upon site conditions represented in your report, the Department will not require any further work at this time. The site will have a status of "inactive".

Please note, any soils generated during future site excavations from the contaminated area must be tested and analyzed by an approved laboratory from New York State's Environmental Laboratory Program (ELAP). If sample results exceed guidance values listed in the Department's STARS Memo #1 (Petroleum Contaminated Soil Guidance Policy), the excavated material will require remediation or proper disposal. For further information, please refer to the Department's website at www.dec.ny.gov/chemical.

Your cooperation is appreciated. If you have any questions, please call me at (716) 851-7220.

Sincerely,

Salvatore A. Calandra, P.E.

Project Manager

SAC:sz

cc:

Mr. James Strickland - NYSDEC, Division of Hazardous Materials - Region 9

Mr. Kent Johnson - NYSDEC, Division of Hazardous Materials - Albany

Mr. Matthew Forcucci - NYS Department of Health

Mr. Paul Dicky - Niagara County Health Department

Mr. Jeff Hall - Army Corps of Engineers, Buffalo District

