



042331
60349

Department of Energy
Oak Ridge Operations
P. O. Box E
Oak Ridge, Tennessee 37831

December 29, 1986

Somerset Group, Inc.
Lew-Port Industrial Park
Balmer Road
Youngstown, New York 14174

Dear Sir:

NFSS POST-REMEDIAL ACTION REPORT 1983-84

I am pleased to inform you that the results of the post-remedial action radiological surveys have been verified and that remedial action on your property has been satisfactorily completed. The property is now in compliance with the standards and guidelines applicable to the remedial actions at the Niagara Falls Storage Site (NFSS). The data supporting the determination are in the enclosed post-remedial action report. This report also describes the radiological surveys and remedial actions conducted on your property and other properties in your area on which appropriate remedial activities were conducted.

A formal certification statement on your property will be forwarded to you in the near future.

Thank you for your cooperation, and if there are any questions, contact me or Mr. Bob Bowles of my staff at (615) 576-4451.

Sincerely,

for *Lowell E. Campbell*
S. W. Ahrends, Director
Technical Services Division

CE-53:Bowles

Enclosure

Received by

JAN 2 1987

ATTACHMENT
NOT RECEIVED

FUSRAP PDCC By FUSRAP PDCC

II-64

STATEMENT OF CERTIFICATION: NIAGARA FALLS STORAGE SITE
VICINITY PROPERTIES ASSOCIATED WITH THE
FORMER MED/AEC OPERATIONS

The U.S. Department of Energy, Oak Ridge Operations Office, Former Sites Restoration Division, has reviewed and analyzed the radiological data obtained following remedial action at Niagara Falls Storage Site vicinity properties that were contaminated by material similar to that stored at the former Lake Ontario Ordnance Works in Lewiston, New York. Based on this analysis of all data collected, the Department of Energy (DOE) certifies that the following property is in compliance with DOE decontamination criteria and standards.

Properties owned by Somerset Group, Inc., including:

A portion of Property A as described in the deed, liber 1503, page 752.

A portion of Property D as described in the deed, liber 1503, page 752.

A portion of Property T as described in the deed, liber 1503, page 752.

A portion of Property U as described in the deed, liber 1503, page 752.

A portion of Property V as described in the deed, liber 1503, page 752.

A portion of Lot 13 along the Central Drainage Ditch as described in the deed, liber 1503, page 752.

This certification of compliance provides assurance that future use of these properties will result in no radiological exposure above applicable guidelines established to protect members of the general public or site occupants.

By:

no L. K. Price
L. K. Price, Director
Former Sites Restoration Division
Oak Ridge Operations Office
U.S. Department of Energy

Date:

2/26/91