

Post-Remedial Action Report
Area 20A-East, 20B, 20B-1, and 20C

Figure 4.15-1
Conceptual Illustration of Contamination

Linde Site, Tonawanda, New York

Bechtel National, Inc.

FUSRAP Program

Date: 6/15/99

File: 129F127.DGN

Job #: 14501-129

Site Map



LEGEND

A-2	Grid Coordinates (1 meter x 1 meter cells)
LIN410 ●	Verification soil sample location and sample number
———	Building Walls
	Area of overhead contamination
	Area of floor or subsurface contamination
	Location exceeding remedial action criteria