

Howell, Debra LRB

From: Barbara Youngberg [bayoungb@gw.dec.state.ny.us]
Sent: Monday, January 10, 2005 4:04 PM
To: Howell, Debra LRB; Leggett, Harold J III LRB; Papura, Thomas R LRB
Subject: RE: CMSA Pile

Debbie - One question - Where were the "CMAS pad area" readings taken, on the pad itself before it was moved, or in the soil surrounding it?

* - CWM's
air station
monitoring well
~200' west
of pad

>>> "Howell, Debra LRB" <Debra.Howell@lrb01.usace.army.mil> 1/10/2005 1:47:59 PM >>>

Barb,
Below is what you requested. Please call Tom or myself if you have any questions. I'll try and call you from home today about 3:00pm if that's OK.
Thanks,
Debbie

Debbie,
I hope this is what you are looking for.
Background at the site prior to final scrap of pad.
Stone parking lot, 4k to 5k. CMAS pad area 10k to 12k. with the 2x2 NaI.

call cost to complete

Paul Jung, RRPT
Corporate Radiation Safety Officer
Health and Safety Officer
Sevenson Environmental Services, Inc.
2749 Lockport Road
Niagara Falls, NY 14305
716-284-0431 x 207
716-285-4201 fax
www.sevenson.com

-----Original Message-----

From: Papura, Thomas R LRB
Sent: Monday, January 10, 2005 7:50 AM
To: Leggett, Harold J III LRB
Cc: Howell, Debra LRB

Subject: FW: CMSA Pile

Information request from Barb Youngberg. Can you pass it on to Severson?

Thanks

-----Original Message-----

From: Barbara Youngberg [mailto:byoungb@gw.dec.state.ny.us]

Sent: Friday, January 07, 2005 3:22 PM

To: Papura, Thomas R LRB

Cc: John Mitchell

Subject: CMSA Pile

Tom - Would you please send me the background count rates measured when the biased samples were collected on the west pile? Thanks.