


Appendix O

Historical Aerial Photographs



Legend

⊕ NFSS TM Wells

**Comparison of Historical Site Operations
Near the IWCS With Current Groundwater
Contamination (Dissolved Total U)**

Material Storage Pile

**This area is crossed by various utilities, including
the Sanitary Sewer line that is impacted from
surface inflows from nearby operations that included
decontamination pads, ground scaring from usage,
and rail-line activities.**

**Material Storage Piles and
Operations Evident Through 1981**



This area is crossed by various utilities, including the Sanitary Sewer line that is impacted from surface inflows from nearby operations that included decontamination pads, ground scaring from usage, and rail-line activities.

Material Storage Piles and Operations Evident Through 1981

Legend

**Comparison of Historical Site Operations
Near the IWCS With Current Groundwater
Contamination (Dissolved Total U)**

1960 Aerial



This area is crossed by various utilities, including the Sanitary Sewer line that is impacted from surface inflows from nearby operations that included decontamination pads, ground scaring from usage, and rail-line activities.

Material Storage Piles and Operations Evident Through 1981



This area is crossed by various utilities, including the Sanitary Sewer line that is impacted from surface inflows from nearby operations that included decontamination pads, ground scaring from usage, and rail-line activities.

Material Storage Piles and Operations Evident Through 1981

Legend

**Comparison of Historical Site Operations
Near the IWCS With Current Groundwater
Contamination (Dissolved Total U)**

1981 Aerial